

PT1744

Manometer Test Tee

The Plumtest Manometer Tee is an essential tool when testing gas lines. Used in conjunction with a Plumtest Manometer and Hand Bellows, it allows the Gas Fitter to complete an efficient and thorough job of the testing procedure.



Instructions for use:

1. Fit the Manometer Tee to the pipe work to be tested. The thread size of the nut is 1" BSP (25mm) and it as a sealing O Ring inside the nut.
2. Fit a Plumtest Hand Bellows to one of the barbs on the tee.
3. Fit a hose to a Manometer on the other barb.
4. Open both ball valves and pump the hand bellows until the testing pressure is reached.
5. Turn off the valve connecting the Manometer tee to the Hand Bellows.
6. Wait the required time to see if there is an indication of a pressure drop.
7. If a pressure drop does occur, visually inspect all joints, rectify as required and repeat the testing procedure. Minor leaks can be found by applying Plumtest Seek a Leak to the joints.